

PESTICIDE CONTAINER DISPOSAL SITE
INSPECTION FORM

Site Name Antelope Valley Date 7/16/79
County San Diego Location San Luis
Responsible Entity San Diego Co Entity Representative Ken Carpenter
Equipment on site None Witnessed by _____

METHOD OF OPERATION

Trench Trench Salvage Operation Yes No
Pit _____
Remarks _____

ACCESSIBILITY Acceptable () Unacceptable

Are roads acceptable leading to site? Y
Litter cleaned? Y Maintained? Y Safe? Y
Remarks _____

WATER POLLUTION Acceptable () Unacceptable

Is site in apparent stream or runoff channel? N
Evidence of flooding or erosion in disposal area? N
Remarks _____

Burn is surrounding area

AIR POLLUTION

Does fire hazard appear to exist? N Any evidence of fires? N
Remarks _____

COVERING CONTROL Acceptable () Unacceptable

Estimated date of last covering 6/30/79
Is open face kept to a minimum? Y Estimated size 15'
Cover depth? 2/3' (24" required)
Remarks _____

PROTECTIVE FENCING Acceptable () Unacceptable

Area fenced _____
Back breaker on each post? Y Fence Height 6/8'
Fencing material metal
Earth berm around fence? Y Earth berm height 2'
Metal gate? Y Locked gate? Y
Warning signs indicating poisonous chemicals disposal area? Y
Sign minimum spacing 60'
Remarks _____

DRAIN SUMP

(✓) Acceptable () Unacceptable

Within fenced area? _____
_____ ft. wide _____ ft deep

Mode of operation _____

Remarks No Sump. Cans are washed at
mixing site

OTHER FACILITIES

() Acceptable () Unacceptable

Building on site? Y 8 ft. wide 10 ft long

Safety equipment and clothing on site? Y Respirator Y Safety Glasses Y
Rubber Gloves Y Rubber Boots Y Rubber Apron Y

Remarks _____

Items needing immediate attention Need water air tank on
site.

Estimated date for followup inspection 10/1/79

Copy of report given/sent to _____
Inspected by _____

Y = Yes N. Obs. = None Observed

N = No or none Picture Nos. NONE