PESTICIDE CONTAINER DISPOSAL SITE
INSPECTION FORM

Site Name Antelope Valley Date 7/16/79

County Landers Location Same

Responsible Entity Landers Co Entity Representative Ken Carpenter

Equipment on site None Witnessed by

METHOD OF OPERATION

Trench Trench Salvage Operation ____ Yes ✓ No

Pit

Remarks

ACESSIBILITY (✓) Acceptable ( ) Unacceptable

Are roads acceptable leading to site? Y

Litter cleaned? Y Maintained? Y Safe? Y

Remarks

WATER POLLUTION (✓) Acceptable ( ) Unacceptable

Is site in apparent stream or runoff channel? N

Evidence of flooding or erosion in disposal area? N

Remarks

Berm is surrounding area

AIR POLLUTION

Does fire hazard appear to exist? N Any evidence of fires? N

Remarks

COVERING CONTROL (✓) Acceptable ( ) Unacceptable

Estimated date of last covering 6/30/79

Is open face kept to a minimum? Y Estimated size 15'

Cover depth? 2/3' (24" required)

Remarks

PROTECTIVE FENCING (✓) Acceptable ( ) Unacceptable

Area fenced

Back breaker on each post? N Fence Height 6/8'

Fencing material Metal

Earth berm around fence? Y Earth berm height 2'

Metal gate? Y Locked gate? Y

Warning signs indicating poisonous chemicals disposal area? Y

Sign minimum spacing 60

Remarks

DRAIN SUMP (✓) Acceptable ( ) Unacceptable

Within fenced area?_____
_____ ft. wide _____ ft deep

Mode of operation

Remarks No Sump. Cans are washed at mixing site

OTHER FACILITIES ( ) Acceptable ( ) Unacceptable

Building on site? Y 8 ft. wide 16 ft long

Safety equipment and clothing on site? Y Respirator Y Safety Glasses Y
Rubber Gloves Y Rubber Boots Y Rubber Apron Y

Remarks

Items needing immediate attention Need water air tank, on site.

Estimated date for followup inspection 10/1/79
Copy of report given/sent to
Inspected by

Y = Yes N. Obs. = None Observed

N = No or none Picture Nos. NONE